

INSPECTION PROCEDURES FOR FULL BODY HARNESS

1. Inspect label. If missing or not legible, remove from service.
2. Check tag for date of manufacture. If beyond service life, remove from service.
3. Inspect dee rings for any cracks or sharp edges/
4. Check mating buckle hardware for cracks and sharp edges. Make sure they connect properly.
5. If leg straps are tongue & grommet style, inspect grommets to insure they are secure and are not elongated.
6. Make sure leg straps do not have extra holes punched into them.
7. Inspect impact indicator on back of shoulder strap. If stitching is released, harness has seen a fall.
8. Inspect webbing.
 - A) Check for frayed, cut or broken fibers.
 - B) Check for burn marks and abrasion.
 - C) Check for paint buildup.
 - D) Check for chemical or heat damage-Brown, discolored or brittle areas.
 - E) Check for UV damage-Fading and presence of splinters on the webbing.
 - F) Inspect stitching-Check for pulled or cut stitching.